

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

October 30, 1979

TELEPHONE: AREA 704
373-4083

Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

Subject: Catawba Nuclear Station
Docket Nos.: 50-413 and 50-414
IE Bulletin 79-14

Dear Mr. O'Reilly:

IE Bulletin 79-14 requested that we verify the seismic analyses for as-built safety-related systems. Presently at Catawba, no systems have reached the completion stage such that re-inspections would be necessary. We believe that our current quality assurance procedures adequately cover all concerns expressed by Bulletin 79-14. The implementation of these procedures is an on-going, integral part of the design and construction of Catawba.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr. *By [Signature]*

ROS/sch

cc: Director, Office of Inspection and Enforcement
Director, Division of Operating Reactors



1375 337

Q 7911210 057

OFFICIAL COPY