



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

NOV 0 6 1979

In Reply Refer To:
RII:JEO
50-325/79-37
50-324/79-36

Carolina Power and Light Company
ATTN: Mr. J. A. Jones
Executive Vice President and
Chief Operating Officer
411 Fayetteville Street
Raleigh, NC 27602

Gentlemen:

This refers to the inspection conducted by J. E. Ouzts of this office on August 31 -September 28, 1979, of activities authorized by NRC Operating License Nos. DPR-71 and DPR-62 for the Brunswick facilities, and to the discussion of our findings held with A. C. Tollison, Jr., at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

AC Lewis

R. C. Lewis, Acting Chief
Reactor Operations and Nuclear
Support Branch

Enclosure:
See Page 2

1608 001

7912180

337
335

4 Q

NOV 0 6 1979

Enclosure:

Inspection Report Nos. 50-325/79-37,
and 50-324/79-36

cc w/encl:

A. C. Tollison, Jr.

Plant Manager

Box 458

Southport, NC 28461

1608 002