

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

December 18, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - DIESEL GENERATOR FIELD RELAY  
COIL (K1) FAILURES - NCR 15P - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
W. T. Cottle on August 27, 1979, in accordance with 10 CFR 50.55(e).  
An interim report was submitted on September 26, 1979. Enclosed is  
our final report.

If you have any questions concerning this matter, please get in touch  
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager  
Nuclear Regulator and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

1644 319

Boia  
5/11

473