



Docket No. 50-346

License No. NPF-3

Serial No. 566

December 27, 1979

RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Director of Nuclear Reactor Regulation
Attention: Mr. Robert W. Reid, Chief
Operating Reactors Branch No. 4
Division of Operating Reactors
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Reid:

Attached are five copies of Small Break Operating Guidelines which have been generated specifically for the Davis-Besse Nuclear Power Station Unit 1 (DB-1). These incorporate the inadequate core cooling guidelines in response to Section 2.1.9 of NUREG-0578 "TMI-2 Lessons Learned Task Force Status Report."

These guidelines are being finalized in DB-1 procedures and are to be in place by December 31, 1979.

Very truly yours,

RPC:TJM:rs

Attachment

cc: R. A. Capra
Project Management Group
Bulletins and Orders Task Force
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dan Garner
Operating Reactors Branch No. 4
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

1654 294

A091
S
1/1