

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

December 12, 1979/7

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT, UNIT B1 - REPORTABLE DEFICIENCY - USE OF
INCORRECT CONCRETE MIX IN SHIELD BUILDING WALL (NCR HNP-B-023)

Initial report of the subject deficiency was made to W. B. Swan,
NRC-OIE, Region II on June 26, 1979. The first interim report was
submitted on July 25, 1979. In compliance with paragraph 50.55(e)
of 10 CFR Part 50, we are enclosing the second interim report of
the subject deficiency. It is anticipated that the final report
will be transmitted to you on or before March 14, 1980. If you
have any questions regarding this subject, please call Jim Domer at
FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager,
Nuclear Regulation and Safety

Enclosure

*B019
S/11*

1671 269

8001030 750

OFFICIAL COPY