

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

January 11, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNITS A1 AND B1 - REPORTABLE DEFICIENCY -
CONTAINMENT ANCHOR BOLT CHAIR WELD DEFICIENCIES (NCR HNP-A-062)

Initial report of the subject reportable deficiency was made to
F. S. Cantrell, NRC-OIE, Region II, on August 2, 1979. The first
interim report was submitted on August 30, 1979. In compliance with
paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the second
interim report of the subject deficiency. It is anticipated that
the final report will be transmitted to you on or before March 19, 1980.
If you have any questions concerning this subject, please call
Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1774 282

3019
SE 1/11