



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V
1990 N. CALIFORNIA BOULEVARD
SUITE 202, WALNUT CREEK PLAZA
WALNUT CREEK, CALIFORNIA 94596

TIC

January 7, 1980

Docket No. 50-228

Aerotest Operations, Inc.
3255 Fostoria Way
San Ramon, California 93583

Attention: Mr. R. L. Newacheck, President

This letter refers to the inspection conducted by Messrs. A. V. Wieder and B. L. Brock of this office on December 13-14, 1979 of activities authorized under NRC License No. R-98. It also refers to the discussion of our inspection findings with Mr. R. L. Newacheck at the conclusion of the inspection.

The areas examined during the inspection included your program for controlling and accounting for special nuclear material pursuant to applicable provisions of Part 70, Title 10, Code of Federal Regulations, and specific requirements of NRC License No. R-98. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with plant personnel and observations by the inspectors.

No items of noncompliance with NRC requirements were identified within the scope of this inspection.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your control and accounting procedures for safeguarding special nuclear materials are exempt from disclosure; therefore, the inspection report will not be placed in the Public Document Room and will receive limited distribution.

1825 358

8001280 460

January 7, 1980

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,


L. R. Norderhaug, Chief
Safeguards Branch

Enclosure:

IE Inspection Report

No. 50-228/79-03 (IE-V-356)

1826 359