



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

License No. 35-11615-01

06 MAY 1980

Clark Inspection Service, Inc.  
Attn: R. L. Clark  
President  
1855 North 105th East Avenue  
Tulsa, Oklahoma 74116

Gentlemen:

Thank you for your letter of April 14, 1980, in response to our letter dated March 24, 1980, and the attached Notice of Violation.

As a result of our review, we find that additional information as discussed with Mr. R. L. Clark by telephone on April 28, 1980, is needed.

Relative to Item 1 of the Notice of Violation, Attachment A of your response does not provide for the documentation of the amount of any occupational dose which an individual may have received during the current calendar quarter. Please submit your plan for corrective action in order to achieve compliance with this aspect of 10 CFR 20.102(a).

Relative to Item 3, please describe the actions you will take to assure that warning signals are maintained in an operable condition at all times.

You should submit the above referenced information within ten (10) days of your receipt of this letter so that we can continue our review of this matter.

Sincerely,

*Glen D. Brown*  
Glen D. Brown, Chief  
Fuel Facility and Material  
Safety Branch

8006300 834