

June 6, 1979

Mr. James G. Keppler, Director
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: LaSalle County Station Unit 2

Vent Stack

NRC Docket Nos. 50-373/374

Dear Mr. Keppler:

Commonwealth Edison notified your office on May 8, 1979 of a possible deficiency in the steel ventilation stack at LaSalle County Station. That notification was made in accordance with 10 CFR 50.55(e). This letter fulfills the 30-day reporting requirement imposed by that regulation.

As was reported, defects identified in the bottom ring of the stack led to the comprehensive non-destructive examination of the affected areas of the stack. A summary of the results of the inspection conducted is provided as an attachment to this letter.

Although it has been determined that no immediate remedial action is required, the permanent repair or reenforcement of the vent stack is now being studied. It is expected that a final report on this deficiency can be provided by October 1, 1979 at which time sufficient evaluation of alternative modification schemes will have been completed.

Please address any questions on this submittal to this office.

POOR ORIGINAL

Very truly yours,

2284 133

L. O. DelGeorge

Nuclear Licensing Administrator

attachment

cc: Director of Inspection & Enforcement

B013, 11