



Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. BOX 1223

ELMA, WASHINGTON 98541

PHONE (206) 249-5001

January 31, 1980  
G03-80-199

U. S. Nuclear Regulatory Commission  
Region V  
1990 North California Boulevard  
Suite 202, Walnut Creek Plaza  
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken  
Director of Regulatory Operations

Dear Mr. Engelken:

Subject: WPPSS NUCLEAR PROJECT NO. 3  
DOCKET NUMBER 50-508  
REPORTABLE DEFICIENCY, 10CFR50.55(e)  
DEFECT/NONCOMPLIANCE REPORT NO. 008

Reference: G03-79-2253, N. O. Strand to R. H. Engelken,  
same subject, dated December 3, 1979.

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on November 2, 1979 of a reportable condition involving the omission of vertical reinforcing steel in the shear wall separating the WNP-3 Fuel Handling Building and the Reactor Auxiliary Building. Attached is our final report concerning this deficiency.

All corrective action discussed in the final report will be implemented prior to our targeted placement of February 15, 1980.

Please contact us if you require additional information.

Very truly yours,

N. O. STRAND  
Managing Director

Attachments

cc: D. Smithpeter - BPA  
WNP-3/5 Files - Richland  
Director of Inspection and Enforcement

1938 123

B019  
SE  
1/1

8002070 312

S