

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III

799 ROCSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

1980

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Energy Supply
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the inspection conducted by Mr. L. A. Reyes of this office on November 2, 3, 5-10, 12-16, 19-30, 1979, of activities at the Davis Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with T. Murray throughout the month and at the conclusion of the inspection on November 30. 1979.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must in-

1934 277

clude a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. F. Heishman, Chief Reactor Operations and Nuclear Support Branch

Enclosures:

- Appendix A, Notice of Violation
- IE Inspection Report No. 50-346/79-29

cc w/encls:

Mr. T. D. Murray, Station
Supertindent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Harold W. Kohn, Ohio Power
Siting Commission
Helen W. Evans, Director
Division of Power
Generation