PILGRIM NUCLEAR POWER STATION RFD # 1 ROCKY HILL ROAD PLYMOUTH, MASSACHUSETTS 02380

SUSTON ECISOR COMPANY

February 5, 1980

BECo Ltr. #80-21

Director, Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Licensee Event Report 80-002/01T-0

Docket Number 50-293 License DPR-35

Gentlemen:

-

The attached Licensee Event Report 80-002/01T-0, Cable Separation Inadequacy, is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.1.1.

If there are any questions on this subject, please contact us.

Respectfully submitted, Wie Lune P. J. McGuire

1940 286

8002110 603

Station Manager Nuclear Operations

MTM:ep

Enclosures: (3 copies) LER 80-002/01T-0

cc: Director (40 copies)
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555