



bcc to DAC:ADM:  
CENTRAL FILES  
PDR:HQ  
LPDR  
~~TIC~~  
NSIC

ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

STATE

January 14, 1980

1-010-13  
2-010-11

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Units 1 and 2  
Docket Nos. 50-313 and 50-368  
License Nos. DPR-51 and NPF-6  
Subsequent Information to I E  
Bulletin 79-24  
(File: 1510.1 and 2-1510.1)

Gentlemen:

In our response to I E Bulletin 79-24, dated October 31, 1979, we identified the Arkansas Nuclear One-Unit 2 refueling water tank overflow line as being a possible freeze hazard. Subsequent evaluation has revealed that this is not the case. The overflow line in question is adequately protected from freezing for the following reasons:

- 1) The temperature of the water in the tank is maintained above 70°F.
- 2) There is no water in the overflow line unless the tank is over-filled.
- 3) The overflow line is 18 inches in diameter.

Thus, no modifications will be made to the overflow line for freeze protection purposes.

Very truly yours,

*David C. Trimble*  
David C. Trimble  
Manager, Licensing

DCT:DEJ:bjm

Q

80 02140

521

1-010-13

2-010-11

Mr. K. V. Seyfrit, Director

- 2 -

January 14, 1980

cc: Mr. W. D. Johnson  
U. S. Nuclear Regulatory Commission  
P. O. Box 2090  
Russellville, Arkansas 72801

Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555