

## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 631 PARK AVENUE

631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

JAN 2 3 1979

Docket Nos. 50-317 50-318

> Baltimore Gas and Electric Company ATTN: Mr. A. E. Lundvall, Jr. Vice President, Supply P. O. Box 1475 Baltimore, Maryland 21203

Gentlemen:

Subject: Combined Inspection 50-317/78-36; 50-318/78-21

This refers to your letter dated December 29, 1978, in response to our letter dated December 12, 1978.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a subsequent inspection of your licensed program.

In regard to your comments concerning Item 2 of the report, we acknowledge that the Rad-Chem Foreman did indicate to our inspector that the company's review of the qualifications of the contractor personnel had not been completed. The observations by our inspector, as stated in the report, were not intended to infer that unqualified personnel may have been inadvertently placed in responsible positions. As you will note, our followup in this area indicated that you were in compliance with the Technical Specification at the time of the outage. If you have further questions in this area, we will be pleased to discuss them with you.

Your cooperation with us is appreciated.

Sincerely,

George A. Smith, Chief Fuel Facility and Materials

/Safety Branch

cc:

R. M. Douglass, Manager, Quality Assurance L. B. Russell, Chief Engineer W. Gibson, General Supervisor, Operational QA R. C. L. Olson, Senior Engineer