

# NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

February 23, 1979

Mr J G Keppler  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42  
50-306 DPR-60

Inoperability of No. 22 Diesel  
Cooling Water Pump

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.(b) since the condition led to operation in a degraded mode permitted by a limiting condition for operation as stated in Specification 3.3.D.

Yours very truly,

  
L. O. Mayer, PE

Manager of Nuclear Support Services

LOM/JAG/deh

cc: Director, IE, USNRC (30)  
Director, MIPC, USNRC (3)  
MPCA  
Attn: J W Ferman

79022800254

-over-

A002  
5/11  
5