APPENDIX A

NOTICE OF VIOLATION

Mount Sinai Hospital Hartford, Connecticut License No. 06-14734-01 Ducket No. 30-13632

Based on the results of an NRC inspection conducted on February 14, 1979, it appears that certain of your activities were not conducted in full compliance with NRC regulations as indicated below:

A. 10 CFR 20.201(b) requires that you make such surveys as may be necessary to comply with all sections of Part 20.

Contrary to this requirement, you failed to make such surveys as were necessary to assure compliance with 10 CFR 20.301, a regulation that describes authorized means of disposing of licensed material contained in waste. Specifically, as of February 14, 1979, you failed to survey for contamination (licensed materials) on swabs prior to allowing patients dispose of them, and on shipping containers prior to disposing of them.

This is an infraction.

B. 10 CFR 20.203(f)(1) and (2), requires that each container of licensed material bear a durable, clearly visible label bearing the radiation caution symbol and the words "Caution, Radioactive Material," and identify the radioactive contents.

Contrary to this requirement, on the day of the spection, February 14, 1979, a basket in your hot lab failed to bear the required label.

This item is a deficiency.

C. 10 CFR 20.401(b) requires that you maintain records showing the results of surveys required by 10 CFR 20.201(b) "Surveys."

Contrary to this requirement, as of February 14, 1979, you failed to maintain records of surveys that you performed to assure compliance with 20.301, "Waste Disposal, General Requirements," a regulation that describes authorized means of disposing of licensed material contained in waste.

This item is a deficiency.

2313 349