

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME:

01	P	A	T	M	I	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	1
---	---

CATEGOR:

01	CON	T
----	-----	---

 REPORT TYPE:

T

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	2	8	9
---	---	---	---	---	---	---	---

 EVENT DATE:

0	8	2	5	7	7
---	---	---	---	---	---

 REPORT DATE:

0	9	0	8	7	7
---	---	---	---	---	---

EVENT DESCRIPTION

02 | During normal operations, restrictions were placed on Decay Heat Removal Pumps which | 80
03 | were found contrary to the pumps operating capability as stated in the FSAR. These | 80
04 | restrictions were created due to the failure of a similar pump at another utility. | 80
05 | | 80
06 | | 80

SYSTEM CODE:

Z	Z
---	---

 CAUSE CODE:

F

 COMPONENT CODE:

Z	Z	Z	Z	Z	Z
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

Z

 COMPONENT MANUFACTURER:

Z	9	9	9
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08 | The NSSS vendor placed the restrictions on the pump due to a failure of a similar | 80
09 | pump at another utility. | 80
10 | | 80

FACILITY STATUS:

E

 % POWER:

1	0	0
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

A

 DISCOVERY DESCRIPTION:

NA

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

13 | NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

 | 80

PERSONNEL INJURIES

14 | NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

 | 80

OFFSITE CONSEQUENCES

15 |

NA

 | 80

LOSS OR DAMAGE TO FACILITY

16 | TYPE:

Z

 DESCRIPTION:

NA

 | 80

PUBLICITY

17 | Included in weekly news release. | 80

ADDITIONAL FACTORS

18 | | 80

19 | | 80

NAME: W. E. Potts

PHONE: 899-3601 Ext. 114

7910250775

GPO 881-667

1482 033