

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE										EVENT TYPE																													
01 PATMI /										00-000000-00										4 / / / /										03																													
CATEGORY										REPORT TYPE										REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
01 CONT										L										L										050-0289										062977										072977									

EVENT DESCRIPTION

02	During normal operations it was noted that the Nuclear Services	80
03	River Water Pump (NR-PIC) shaft failed while the pump was	80
04	operating. NRWP (NR-PIA) was available to supply cooling	80
05	water requirements in case of an Engineered Safeguards	80
06	actuation. (77-13/34)	80

SYSTEM CODE			CAUSE CODE			COMPONENT CODE			PRIME COMPONENT SUPPLIER			COMPONENT MANUFACTURER			VIOLATION		
WB			D			PUMAXX			A			P / / / 5			N		

CAUSE DESCRIPTION

08	The Operations Department never received the orders to	80
09	restrict the operation of the pump before it could be	80
10	overhauled. [Peerless Pump Co., 1 stage, 1185 rpm, 24 H x 3 bowl]	80

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
E			100			NA			A			NA		

FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE		
Z			Z			NA			NA		

PERSONNEL EXPOSURES

NUMBER			TYPE			DESCRIPTION		
000			Z			NA		

PERSONNEL INJURIES

NUMBER			DESCRIPTION		
000			NA		

OFFSITE CONSEQUENCES

15	NA	80
----	----	----

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION		
Z			NA		

PUBLICITY

17	Included in weekly news release.	80
----	----------------------------------	----

ADDITIONAL FACTORS

18	NR-PIA was lined-up and selected for R.S. operations within	80
19	four hours.	80

NAME: W.E. Potts PHONE: 929-3661 (ext 114)

7910250784