



435 Sixth Avenue
Pittsburgh, Pennsylvania
15219

(412) 456-6000

October 19, 1979

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

ATTENTION: MR. BOYCE H. GRIER, DIRECTOR

SUBJECT: Beaver Valley Power Station - Unit No. 2
Reactor Containment Liner - Overlay Pad
Fillet Weld Crack
Docket No. 50-412
Significant Deficiency Report No. 78-03

Gentlemen:

Pursuant to the requirements of 10CFR50.55(e), Duquesne Light submitted a final written report on the subject problem March 22, 1979. Your review of that submittal has resulted in our revision of the final report to delete both the Proprietary Notice and Disclaimer of Responsibility from Enclosure 1 of the report. We believe that these revisions satisfy your earlier concerns and, therefore, herewith submit the revised final report.

If you have further questions regarding our submittal, we can meet with the appropriate Nuclear Regulatory Commission technical personnel at their convenience.

DUQUESNE LIGHT COMPANY

By E. J. Woolever
E. J. Woolever
Vice President

cc: Mr. John G. Davis (15)
Mr. William G. McDonald

1215 152

79102600841