

APPENDIX A

NOTICE OF VIOLATION

Florida Power Corporation  
Crystal River 3

License No. DPR-72

Based on the NRC inspection August 13-17, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Technical Specification 6.8.1, Written Procedures shall be established, implemented and maintained, specifically covering the activities stated in paragraph (c), "surveillance and test activities of safety related equipment." The Surveillance Procedure SP-113, Power Range Nuclear Instrumentation Calibration, requires Sections 1, 2 and 7 to be completed in order to reset high flux trip setpoints.

Contrary to the above, during the preparation for the three pump operation on August 16, 1979, the technician who performed the above calibration did not, as witnessed by the inspectors, complete the procedure data sheets for Sections 1 and 7.

This is an infraction.

1217.116

7910260 39.6