

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
 (TEMPORARY FORM)

CONTROL NO: 57

FILE: INCIDENT REPORT

FROM:	Metropolitan Edison Co Lebaron, Pa J G Herbein	DATE OF DOC	12-31-74	DATE REC'D	1-6-75	LTR	TWK	RPT	OTHE
TO:	Mr O'Reilly	ORIG	none signed	CC	OTHER	SENT AEC PDR	XX		
CLASS	UNCLASS XXXXXX	PROP INFO	INPUT	NO CYS REC'D	1	DOCKET NO:	50-289		

DESCRIPTION:

Ltr re Abnormal Occurrence #74-33 on 12-30-74 concerning the failure of a heat pump suction valve.....

ENCLOSURES:

**POOR ORIGINAL**

PLANT NAME: Three Mile Island #1

FOR ACTION INFORMATION 1-8-75 ehf

BUTLER (S)	SCHWENGER (S)	ZIEMANN (S)	REGAN (E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK (S)	STOLZ (S)	DICKER (E)	LEAR (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
PARR (S)	VASSALLO (S)	KNIGHTON (E)	SPEIS (S)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL (S)	PURPLE (S)	YOUNGBLOOD (E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION


<del>ONE FILE</del>	TECH REVIEW	DENTON	LIC. ASST.	A/T IND
AEC PDR	SCHROEDER	GRIMES	DIGGS (S)	BRAITHMAN
DOGC, ROOM P-506-A	MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
CLINTZING/STAFF	KNIGHT	KASTNER	GOULBOURNE (S)	B. HURT
CASE	SPANICKI	BALLARD	KREUTZER (E)	
GIAMBUSO	CHAO	SPANGLER	LEE (S)	PLANS
BOYD	ESTELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	HOUSTON	ENVIRO	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	NOVAK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	ROSS	DICKER	SHEPPARD (S)	E. COUPE
GOLLER (S)	IPPOLITO	KNIGHTON	SLATER (E)	D. THOMPSON (2)
P. COLLINS	TEDESCO	YOUNGBLOOD	SMITH (S)	KLECKER
DENISE	LONG	REGAN	TEETS (S)	EISENHUT
REG CFR	LAINAS	PROJECT LDR	WILLIAMS (E)	
FILE & REGION (2)	BEMAROYA	HARLESS	WILSON (S)	
V.T.R. WILSON	STEELE VOLIMER		INGRAM (S)	

1482 212

EXTERNAL DISTRIBUTION

-LOCAL PDR <u>Harrisburg, Pa</u>	(1)(2)(10)-NATIONAL LABS	1-PDR SAN/LA/ME
-TIC(ABERNATHY)	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
-NSIC(BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSEN, ORNL
1-ASLB	NEWMARK/BLUME/ACBASIAN	1-AGMED(RUTH GUSEMAN)
1-NEWTON ANDERSON		RM B-127 G.T.
5-ACRS SENT TO LIC. ASST. Teets		1-J. RUNKLES, RM E-201 G.T.

7910260 529 S



METROPOLITAN EDISON COMPANY

SUBSIDIARY OF GENERAL PUBLIC UTILITIES CORPORATION

OFFICE BOX 240 LEBANON, PENNSYLVANIA 17042

TELEPHONE 717-272-5061

December 31, 1974

Mr. J.P. O'Reilly, Director  
Directorate of Regulatory  
Region I  
631 Park Avenue  
King of Prussia, Pa. 19406

POOR ORIGINAL

JB

Operating License DPR-50  
Docket 50-289

Subject: Abnormal Occurrence No AO 74-33

Dear Mr. O'Reilly:

This telegram is to confirm a conversation between Mr. Bert Davis (Region I-DRO) and J.G. Herbein (TMI-Station Superintendent) at 1430 hours 30 December 1974.

The following report is submitted in accordance with paragraph 6.7.2.a.4 (page 6-11) of the technical specifications.

On 30 December, while conducting a pretest valve line up in preparation for high and low pressure injection surveillance testing, the TA decay heat pump suction valve (DH-V5A) from the Borated Water Storage Tank failed to close.

The motor circuit breaker for valve DH-V5A was reset and the valve was successfully opened and closed using the remote push button operator in the control room. Valve DH-V5B was also opened and closed successfully.

The high and low pressure injection surveillance test was resumed and completed satisfactorily.

Investigation into the cause of the DH-V5A valve motor circuit breaker trip indicated the circuit breaker tripped on over current when the valve motor was started in the close direction.

Further investigation indicated the over current condition could have been caused by valve stem binding within the valve packing due to lack of valve stem lubrication.

Lubricant was applied to the valve stems and the DH-V5A valve was successfully cycled eight times.

1482 213

Very truly yours,

J.G. Herbein

57