



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

D. L. ASWELL
Vice President-Power Production

August 22, 1979

DOCKET NO. 50-382

LPL 11831
Q-3-A14.39
3-A1.01.04

Mr. K. V. Seyfrit
Director
United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Dear Mr. Seyfrit:

This will reply to your letter of August 20, 1979, concerning the deficiencies observed and reported by LP&L QA personnel with regard to the concrete placement by Fegles Power Service during placements 521-A and 521-B on August 8, 1979.

LP&L intends to comply fully with the plans and direction as described in your letter, all items except your No. 9 having been included as a part of the LP&L QA Stop Work Order No. 6 issued at 8:50 A.M. on August 17, 1979. Notification to the NRC will be provided as you requested in Item 9.

We do wish to point out that your Item 4 refers to Ebasco Specification 1544.472 which should be Ebasco Specification 1564.472 for concrete placement.

As we have advised members of your staff, it is LP&L's intent to promptly correct any deficiencies in an acceptable manner. LP&L's Construction Manager and Concrete Contractor have been so advised.

Yours very truly,

D. L. Aswell

DLA:vcr

1523 003

5 7912070 / 50