

## APPENDIX A

## NOTICE OF VIOLATION

Tennessee Valley Authority

License Nos.: CPPR-150  
CPPR-151  
CPPR-152  
CPPR-153

Based on the results of the NRC inspection conducted on October 3-5, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

- A. Section II.B.3 of Attachment B to the Construction Permits required that detailed records of all construction monitoring data will be maintained for use by NRC compliance inspectors and technical staff. The records will contain quarterly summaries documenting the detection of impacts (instances where feedback criteria were exceeded) and, if necessary, the resulting mitigating action and subsequent recovery in water quality.
1. Contrary to the above, pH of the east holding pond discharge to Dixon Creek was reported to have exceeded the maximum assigned limit of 9.0 on February 14, 15, and 20, 1978; however, no mitigating action subsequent to the release was defined.
  2. Contrary to the above, on March 20, 1978, the licensee failed to report excursion of the east holding pond discharge pH above the maximum assigned limit of 9.0. The pH recorded was 9.6.

This is a deficiency.