



TEXAS INSTRUMENTS

INCORPORATED

MATERIALS & ELECTRICAL PRODUCTS GROUP

December 15, 1978

U.S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Attn: Mr. George H. Smith, Chief
Fuel Facility and Materials Safety Br.

Gentlemen:

In accordance with 10 CFR 2.201, Texas Instruments (TI) is responding to your letter of December 6, 1978, "Inspection 70-33/78-15".

The case of noncompliance as itemized in your Appendix A is briefly described below with out associated (1) corrective steps which have been taken and our results achieved, (2) corrective steps which will be taken to avoid further items of noncompliance, and (3) the date when full compliance will be achieved.

INFRACTION: Inadequate MSQ postings at work station locations 5, 8, 35, 36, 37, 38, and 39 and lack of MSQ posting on two transportation/storage carts.

(1) Corrective actions taken were:

- (a) All postings of MSQ's have been accomplished in accordance with current approved limits.
- (b) A total review of all work station locations and transportation/storage carts has been accomplished to assure compliance of all MSQ postings with currently approved limits.

(2) Corrective steps which will be taken to avoid further items of noncompliance are:

- (a) The incorporation of approved MSQ postings into the formal monthly criticality safety inspection.

(3) Full compliance has already been achieved.

7901180314

Mr. George H. Smith
December 15, 1978
Page 2

Please call if you have any questions about our response to this item.

Sincerely,

Calvin M. Hopper

Calvin M. Hopper
Manager, Nuclear Safety

/ck