

TELEPHONE REPORT

FACILITY: Sequoyah 1 and 2 DOCKET #: 50-327
50-328

DATE: February 5, 1979 TIME: 1:20 pm LIC. OCC. #: _____

SUBJECT: Error in Design of Small Line Supports

DESCRIPTION OF OCCURRENCE: TVA notified RII that the movement of the steel
containment vessel lines was overlooked in the design of the small line
supports. The small lines are being re-analyzed and supports will be
re-designed per the analysis. TVA is evaluating for generic implications.
Written report due 3/7/79.

M. House
SIGNATURE