



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

January 29, 1979

2-019-19

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
Nos. 50-368/78-33 and 50-368/78-34
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning an inoperable Containment Building Pressure Channel and the improper installation of an Excore Detector Channel.

Very truly yours,

A handwritten signature in cursive script that reads "Daniel H. Williams".

Daniel H. Williams
Manager, Licensing

DHW:BI:vb

Attachment

cc: Mr. John G. Davis, Acting Director
Office of Inspection & Enforcement
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

790205012