

VERMONT YANKEE NUCLEAR POWER CORPORATION

SEVENTY SEVEN GROVE STREET  
RUTLAND, VERMONT 05701

B.4.2.1  
WVY 79-138

REPLY TO:  
ENGINEERING OFFICE  
TURNPIKE ROAD  
WESTBORO, MASSACHUSETTS 01581  
TELEPHONE 617-366-9011

November 26, 1979

United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Attention: Office of Inspection and Enforcement  
Mr. Boyce H. Grier, Director

References: (1) License No. DPR-28 (Docket No. 50-271)  
(2) USNRC Letter to VYNPC dated March 12, 1979;  
IE Bulletin 79-03  
(3) USNRC Letter to VYNPC dated September 14, 1979;  
Inspection Report 50-271/79-12

Dear Sir:


Subject: Supplemental Response to IE Bulletin 79-03

Information provided in Reference (3) indicates that Vermont Yankee's original response to Bulletin 79-03 was inadequate because our answer did not directly address the Bulletin items. Consequently, a search of purchase order documentation has been conducted and it can be concluded that ASME SA-312, type 304 or other welded pipe manufactured by Youngstown Welding and Engineering Company has never been used at Vermont Yankee.

We trust this resolves the outstanding issue regarding IE Bulletin No. 79-03. Should you have any additional questions, please contact us.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

  
D. E. Moody  
Manager of Operations

RJW/dmp

1674 268

8001020

719