

UNION CARBIDE CORPORATION  
MEDICAL PRODUCTS DIVISION  
1000 ...  
... ..

February 8, 1980

Mr. ROYCE B. Grier  
U. S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement, Region 1  
631 Park Avenue  
King of Prussia, PA 19406

Dear Mr. Grier:

At approximately 2400 hours on 7 February 1980, the control rod withdrawal inhibit on the intermediate power level period monitor was found set at less than the required 30 second setpoint pursuant to Technical Specification 3.2.3. It is believed to have been moved inadvertently during a channel check performed approximately 8 hours earlier. The 10 second reverse and the 3 second scram setpoints remained operable. The instrument was corrected immediately. This is not a repetitive situation.

This telecopy confirms a telephone notification to Mr. E. B. McCabe of your office at 1415 hours today. A written report will be submitted within 14 days pursuant to Technical Specification 6.5.3.a.(1)(b).

Yours very truly,



MARCUS H. VOTH  
Manager  
Nuclear Operations

MHV:ltm

Max  
S-10

S

8002140 504