

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

6	1	A	R	A	N	O	1	2	0	0	-	0	0	0	0	-	0	0	1	1	1	1	4	5	5
8	9	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	57	CAT	58													

CONT

6	1	REPORT SOURCE	L	6	0	1	5	0	0	0	3	6	8	7	0	5	1	4	7	9	8	0	6	1	2	7	9	9
8	9	60	61	DOCKET NUMBER	66	60	74	75	76	77	78	79	80	REPORT DATE														

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

6 2 During Mode 3 operation, Emergency Feedwater flow control valve,

6 3 2CV-1025-1 failed open and would not respond to the demand

6 4 signal. The open position is the required position for EFAS; therefore,

6 5 the flowpath to the A Steam Generator would be unaffected in

6 6 an emergency situation. This occurrence is similar to

6 7 50-368/78-028 and 78-009. Reportable per T.S.6.9.1.9 (b).

6 8

6 9	SYSTEM CODE	W   B	11	CAUSE CODE	E	12	CAUSE SUBCODE	A	13	COMPONENT CODE	V   A   L   V   I   P	14	COMP SUBCODE	A	15	VALVE SUBCODE	Z	16		
7	LER NO	EVENT YEAR	19	21	22	23	SEQUENTIAL REPORT NO.	0   3   5	24	25	26	27	28	29	30	REPORT TYPE	L	31	REVISION NO	0
8	REPORT NUMBER	21	22	23	24	25	OCCURRENCE CODE	0   3	26	27	28	29	30	31	32		33	34		
9	ACTION TAKEN	FUTURE ACTION	7   9	18	19	20	EFFECT ON PLANT	2   0	21	22	23	24	25	26	27	ATTACHMENT SUBMITTED	N   0	28	29	30
10	SHUTDOWN METHOD	HOURS	10   0   0   0   0	35	36	37	11	12	13	14	15	16	17	18	NPRD-4 FORM SUB	N   J	31	32	33	
11	COMPONENT MANUFACTURER	19   9   9	26	27	28	29	30	31	32	33	34	35	36	37	PRIME COMP SUPPLIER	N   N	38	39	40	

6 10 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

6 11 Investigation revealed the pressure switch that

6 12 serves as a limit switch for 2CV-1025-1 malfunctioned.

6 13 The switch was repaired and the valve was returned

6 14 to the operable status approximately four hours after

6 15 the failure, meeting the requirement of Action Statement T.S.3.7.1.2

6 16	FACILITY STATUS	% POWER	10	11	12	13	OTHER STATUS	NA	30	METHOD OF DISCOVERY	NA	31	DISCOVERY DESCRIPTION	32
7	B   28	0   0   0	29	NA	44	45	46							80

6 17	ACTIVITY CONTENT	AMOUNT OF ACTIVITY	35	36	37	38	39	40	41	42	43	44	45	46	47
7	2   3	2   3	34	NA	44	45	46	47	48	49	50	51	52	53	54

6 18	PERSONNEL EXPOSURES NUMBER	TYPE	37	38	39	40	41	42	43	44	45	46	47	48	49
7	0   0   0	Z	37	38	39	40	41	42	43	44	45	46	47	48	49

6 19	PERSONNEL INJURIES NUMBER	DESCRIPTION	41	42	43	44	45	46	47	48	49	50	51	52	53
7	0   0   0	40	NA	42	43	44	45	46	47	48	49	50	51	52	53

6 20	LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION	43	44	45	46	47	48	49	50	51	52	53	54	55
7	2   42	NA	44	45	46	47	48	49	50	51	52	53	54	55	56

6 21	PUBLICITY RELEASE DESCRIPTION	45	46	47	48	49	50	51	52	53	54	55	56	57	58
7	N   44	NA	46	47	48	49	50	51	52	53	54	55	56	57	58

6 22	NRC USE ONLY	59	60	61	62	63	64	65	66	67	68	69	70	71	72
7	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73

NAME OF PREPARED Chris N. Shively

PHONE 501/968-2519

7906180 568

S