

## LICENSEE EVENT REPORT

EXHIBIT A

## CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

6	1	A	R	A	N	O	2	0	0	-	0	0	0	0	4	1	1	1	1	4	5
7	8	9	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	31	32	33	34	35	36	37	38	39	40	CAT 58

CON'T

6	1	REPORT SOURCE	L	J	6	0	5	0	1	0	3	1	6	8	7	0	1	5	1	4	7	1	9	8	0	1	6	1	2	1	7	1	9	9	
7	8	60	61	DOCKET NUMBER	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

- 0 2 During Mode 3 operation, while utilizing the steam driven Emergency Feedwater Pump, 2P7B, for normal auxiliary feed, supply valves, 2CV-1039-2 and 2CV-1076-2, to Steam Generator, 2E24B, would not respond to a Control Room demand signal. The 2P7A feedwater loop to 2E24B was declared inoperable. This occurrence is similar to 50-368/79-026. Reportable per T.S.6.9.1.9 (b).

7	8	9	80
---	---	---	----

2	9	SYSTEM CODE	W	B	11	CAUSE CODE	E	12	CAUSE SUBCODE	A	13	COMPONENT CODE	V	A	L	V	0	P	14	COMP SUBCODE	A	15	VALVE SUBCODE	Z	16	REVISION	0					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39

17	LER NO	REPORT NUMBER	7	9	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	
18	ACTION TAKEN	FUTURE ACTION	B	Z	18	19	Z	Z	Z	Z	Z	0	3	7	0	3	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- 1 0 Unit was placed in Mode 5 operation, due to an unrelated problem, meeting the requirements of Action Statement T.S.3.7.1.2. Investigation revealed a blown fuse in the 2CV-1039-2 circuitry and a stuck relay overriding the 2CV-1076-2 operation. Repairs were made & valves proven operable.

7	8	9	80
---	---	---	----

1	5	FACILITY STATUS	B	28	0	1	0	0	29	NA	OTHER STATUS	30	METHOD OF DISCOVERY	A	31	NA	DISCOVERY DESCRIPTION	32											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

1	6	RELEASED	Z	33	Z	34	NA	AMOUNT OF ACTIVITY	35	NA	LOCATION OF RELEASE	36																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

1	7	PERSONNEL EXPOSURES	0	0	0	37	Z	38	NA	DESCRIPTION	39																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

1	8	PERSONNEL INJURIES	0	0	0	40	NA	DESCRIPTION	41																				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

1	9	LOSS OF OR DAMAGE TO FACILITY	Z	42	NA	TYPE	DESCRIPTION	43																					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

1	10	PUBLICITY	N	44	NA	ISSUED	DESCRIPTION	45																					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

1	11	NRC USE ONLY	501/968-2519																										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

NAME OF PREPARER Chris N. Shively

PHONE 501/968-2519

7906180 587

S