



~~MATERIAL TRANSMITTED HEREWITH  
CONTAINS SENSITIVE INFORMATION~~  
UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30303

MAR 15 1979

Report Nos.: 50-250/79-2 and 50-251/79-2

Licensee: Florida Power and Light Company  
Advanced Systems and Technology  
P. O. Box 529100  
Miami, Florida 33152

Facility Name: Turkey Point 3 and 4

Docket Nos.: 50-250/79-2 and 50-251/79-2

License Nos.: DFR-31 and DPR-41

Safeguards Group No.: IV

Inspection at Turkey Point Site near Homestead, Florida

Inspector: *R. J. Hennessey, Jr.* 3/13/79  
Date Signed

Approved by: *William J. Tobin* 3/15/79  
Date Signed  
F. P. Gillespie, Section Chief, Safeguards Branch

SUMMARY

Inspection on February 4-7, 1979

Areas Inspected

This routine unannounced off-shift inspection involved 21.5 inspector-hours onsite in the areas of access control (ID authorization and badging), access control (search), access control (personnel escorting), access control (vehicle escorting), alarm stations, physical barriers (protected area), and vital area access control.

Results

Of the 7 areas inspected, no apparent items of noncompliance or deviations were identified in 6 areas; one apparent item of noncompliance was found in one area (Deficiency - failure to maintain positive control of access to containment during maintenance - paragraph 11).

S-F2 99-26P  
Copy 7 of        Copies  
This report is for internal use only and is not to be distributed without specific approval of NRC-II

790326 0127