LICENSEE EVENT REPORT

CONTROL BLOCK:
1 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 5
CON'T O 1 SOURCE L 6 0 5 0 0 0 3 3 8 7 0 3 2 0 7 9 8 0 4 1 8 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
[0] The Unit 1. Control Room Emergency Ventilation System charcoal filters failed the
[0]3 [eighteen month periodic test done in accordance with Technical Specification 4.7.7.1.]
[0 4 Consequences were limited due to the availability of the Control Room bottled air
0 5 pressurization system and the two Control Room air conditioning systems. This event
[0 6] [did not jeopardize the health and safety of the general public. Reportable pursuant
0 7 to T.S. 6.9.1.9.b.
0 8 60
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 27 27 27 28 29 30 31 32 31 32 32 33 34 39 35 36 37 37 40 41 31 42 43 43 44 47 47 47 47 47
The charcoal filters in the Emergency Ventilation System have been used during routine
[1] [functional testing to insure operability of the system. The two originally installed
[1]2 [filters' absorption capabilities had been reduced from the required 99.95 percent
[1]3 efficiency to 98.87 and 99.21 percent efficiency, respectively, as indicated by the
[1]4] [freon absorption test. New charcoal filters have been installed.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 9 8 29 NA B 31 Surveillance Inspection 7 8 9 10 10 12 13 44 45 46 46
1 6 E 33 Z 34 NA
1 7 0 0 0 37 Z 38 NA 7 8 9 REPSONNEL IN URBES
NUMBER DESCRIPTION (41) NOMBER DESCRIPTION (41) NA 1 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA NA 1 9 Z (42) NA
PUBLICITY ISSUED DESCRIPTION 45 TO 1240409 NRC USE ONLY N
NAME OF PREPAREN. R. Cartwright PHONE: 703-894-5151