



April 5, 1979

JAMES S. GRANT

Vice President
Energy Supply
(419) 259-5232

Docket No. 50-346
License No. NPF-3
Serial No. 1-55

Mr. James G. Keppler
Regional Director, Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

After reviewing our records, an error was discovered in two sections of the recently submitted 1978 Annual Environmental Operating Report for Davis-Besse Unit No. 1. Please find enclosed a revised index and corrections for each of the two sections.

If you have any questions concerning these sections, please contact us.

Yours very truly,

JSG:Csn

Enclosure

CC: Director, Office of Inspection and Enforcement
Director, Office of Management and Program Analysis
Chief, Division of Safety and Site Analysis

Handwritten: A007
S
11

Table of Contents

Limiting Conditions for Operation

I	Maximum Temperature	2.1.1	
II	Reserved	2.2	
III	Chlorine Monitoring	2.3.1	1
IV	pH Monitoring	2.3.2	
V	Sulfates Monitoring	2.3.3	

Environmental Surveillance

VI	Water Quality Analysis	3.1.1.a.1	
VII	Chemical Usage	3.1.1.a.2	
VIII	Chlorine Monitoring	3.1.1.a.3	1
IX	Plankton Studies	3.1.2.a.1	
X	Benthic Studies	3.1.2.a.2	
XI	Fisheries Population Studies	3.1.2.a.3	
XII	Ichthyoplankton	3.1.2.a.4	
XIII	Fish Egg and Larvae Entrainment	3.1.2.a.5	
XIV	Fish Impingement	3.1.2.a.6	
XV	Bird Collisions	3.1.2.b.1	
XVI	Vegetation Survey	3.1.2.b.2	
XVII	Environmental Radiological Monitoring	3.2	

Special Surveillance and Study Activities

XVIII	Operational Noise Surveillance	4.1
XIX	Fish Impingement Study	4.2
XX	Chlorine Toxicity Study	4.3

2.3.1 Biocides

Chlorine was the only biocide used at Davis-Besse in 1978. Monitoring of chlorine residuals is covered by the Station's NPDES Permit. During the year, there was one violation of the limits on free residual chlorine occurring July 10, 1978. This violation was reported in LER NP-10-78-01.

1

3.1.1.a.3 Chlorine Monitoring

See Section 2.3.1 - Biocides

| 1