



Carolina Power & Light Company

August 2, 1979

110

FILE: NG-3513 (B)

SERIAL: GD-79-1974

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

RECEIVED  
AUG 22 1979

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 AND 2  
DOCKET NOS. 50-325 AND 50-324  
LICENSE NOS. DPR-71 AND DPR-62  
RESPONSE TO IE BULLETIN 79-14

Dear Mr. O'Reilly:

Bulletin 79-14, July 2, 1979, and Revision 1 to the bulletin, July 18, 1979, requested that all licensees verify that plant seismic analyses had used as-built piping and support configuration. This letter documents our compliance with the requirements of Bulletin 79-14.

The Brunswick Plant was nearing the completion of an extensive seismic reanalysis and as-built configuration verification when Bulletin 79-14 was issued. This entire program has been the subject of several meetings and many letters between CP&L and the NRC staff. CP&L letter GD-79-1844 from Mr. E. E. Utley to Mr. T. A. Ippolito with a copy to you summarized our actions in this matter. This letter, along with the data previously supplied to the NRC staff referenced in the letter, satisfies the requirements of Bulletin 79-14.

We trust that this information is suitable for your use. If you have any further questions, please do not hesitate to call my staff.

Yours very truly,

B. J. Furr  
Manager

Generation Department

CSB/jga\*

cc: Director, Office of Inspection & Enforcement  
Director, Division of Operating Reactors

2031 211

790337  
OFFICIAL COPY

2908300588