

REGION I

8003040061

DETAILS

1. Person Contacted

Mr. Randy Mason

2. Expiration of License

The inspector contacted the Pennsylvania Emergency Management Agency and was informed by letter dated November 28, 1979 that the byproduct material possessed under license 37-11695-01 would be picked up by them and returned to their Western Area Headquarters on or before November 30, 1979. The inspector contacted the licensee on January 8, 1980 and was informed that the byproduct material had been picked up by the Pennsylvania Emergency Management Agency. Additionally, the licensee informed the inspector he no longer possessed any byproduct material and wished to have his license terminated.

3. Evaluation by the Regional Office

Region I has evaluated the information supplied by the licensee and determined that a closeout survey is not necessary and that the license should be retired.