

8005071710

APPENDIX A

NOTICE OF VIOLATION

Sun Shipbuilding and Drydock Company
Chester, Pennsylvania 19013
License No. 37-02500-01

Docket No. 30-6073

Based on the results of an NRC inspection conducted on February 22, 23 and 27, 1980, it appears that one of your activities was not conducted in full compliance with NRC regulations as indicated below:

Condition 15 of your license requires that licensed material be possessed and used in accordance with the statements, representations and procedures contained in your application dated June 2, 1977.

Attachment 4 to this application, "Standard Operating Procedure For Safe Handling of Radioactive Material," requires that the radiographer rope off the restricted area perimeter and post "Caution - Radiation Area" signs along this perimeter.

Contrary to this requirement, on February 20 and 21, 1980, radiographers in your employ failed to either rope off or post signs at the perimeter of the restricted area.

This is an infraction.

APPENDIX B

NRC INSPECTORS REQUIRING ACCESS ON BACKSHIFTS AT
SUN SHIPBUILDING AND DRYDOCK COMPANY

1. Ms. Myu Campbell
2. Mr. Francis Costello
3. Dr. John Glenn
4. Mr. Phillip Jerman
5. Mr. John Kinneman
6. Mr. Barry O'Neill
7. Mr. Claude Rowe
8. Mr. Charles Stearns