CORRECTED COPY

U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No.	30-4576/80-01	and the second			
Docket No.	30-4576				
License No.	20-00277-03	Priority	I	Category	В
Licensee:	40 North Av	perations, Incom enue Massachusetts			
Facility Nam	me: <u>Techni</u>	cal Operations, Avenue, Burlingt	Inc.	1150++5	
	conducted: F	ebruary 14, 1980	the	3	<u>-3-80</u> ate signed
Approved by	and the second s	A O Mal	Under	d	ate signed
		ntock, Chief, Ma tion Section, FF		iological d	até signed

Inspection Summary:

Inspection on February 14, 1980 (Report Number 30-4576/80-01)

Areas Inspected: Announced, special inspection to review the decontamination and decommissioning of the licensee's facility at 40 South Avenue including: review of survey methods and reports, physical inspection of the premises and a confirmatory radiation survey.

<u>Results</u>: No items of noncompliance were identified. Survey results agree with licensee's and indicate the facility meets the "Guidelines for Decontamination of Facilities and Equipment Prior to Release for Unrestricted Use."

8006050 622

Region I Form 12 (Rev. April 77)