

APPENDIX A

NOTICE OF VIOLATION

Peabody Testing Services  
Hartford, Connecticut 06114  
License No. 12-00622-07

Docket No. 30-4041

Based on the results of an NRC inspection conducted on February 4, 1980, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC License as indicated below:

10 CFR 20.203(c)(2) requires that you control access to high radiation areas that have been established for periods of 30 days or more by one of three methods, one of which is to equip each entrance, or access point, with a control device which shall energize a conspicuous visible or audible alarm signal in such a manner that the individual entering the high radiation area and the licensee or supervisor, of the activity, are made aware of the entry.

Contrary to this requirement, as of February 4, 1980, the control device which you installed to meet this requirement was inadequate in that it allowed the entry gate to be opened wide enough for an individual to enter your high radiation area without energizing the audible alarm signal.

This is an infraction.

8006090 J51