

✓ To: B. H. Grier, RO

FS&EB ACTION CONTROL FORM

A. Action Code FO#282

Name of Licensee and Facility Metropolitan Edison Co. (Three Mile Island)

Docket No. or License No. 50-289

Title Control Rod Testing

Origin RO:I Date Rec'd 12/26/73

B. FS&EB Branch Coordinator:

Bryan \_\_\_\_\_ Dreher X H. D. Thornburg \_\_\_\_\_

Ellis \_\_\_\_\_ Paulus \_\_\_\_\_

C. Action Requested of:

ADREMP \_\_\_\_\_ MS&POB \_\_\_\_\_ EPB \_\_\_\_\_ RPB \_\_\_\_\_ ADCO X

OB \_\_\_\_\_ CB \_\_\_\_\_ TAB \_\_\_\_\_ OOE \_\_\_\_\_ REGION \_\_\_\_\_

Date Requested 1/4/74 Completion Requested by 1/31/74


Reference Report No. 50-289/73-22 and memo E.J. Brunner to H.D. Thornburg  
undated.

D. Action Requested: Please review the above referenced report and evaluate  
as to whether the required tests should be run or can they accept tests  
at a similar facility.

E. Date Action Completed \_\_\_\_\_ 1419 338

Close-out (Date & Method) \_\_\_\_\_

Comments: If completion date is not consistent with your work  
schedule, please let us know.



7910160655

*Harold D. Thornburg*  
Harold D. Thornburg, Chief  
Field Support & Enforcement Branch  
Directorate of Regulatory Operations