

APPENDIX A

Metropolitan Edison Company  
ATTN: Mr. R.O. Arnold, Vice President  
P.O. Box 542  
Reading, Pennsylvania 19603

NOTICE OF VIOLATION

Gentlemen:

Based on the results of an AEC inspection conducted on September 10-12, 1974, it appears that one of your activities was not conducted in full compliance with AEC regulations and the requirements of your license as indicated below.

10CFR73.40 requires that the Security Plan submitted by the licensee be followed after March 6, 1974. Section 2.3 of the Security Plan's Administrative Procedure AP1011.1, Revision 0, dated February 13, 1974 states that the individual issued a key for a security area lock is responsible for the area under that key's control until the area is again secured and the key is returned.

Contrary to the above, the AEC inspector, after observing a gate to a security area to be open and apparently not under control, did walk unescorted through this gate and then gain entrance to the Auxiliary Building without verification of the propriety of such entrance being attempted or accomplished.

(Severity Category II)  
(Civil Penalty \$4000)

1420 104

7910160726