

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-123/79-01

Packet No. 50-123

License No. R-79

Licensee: The University of Missouri - Rolla
School of Mines and Metallurgy
Rolla, MO 65401

Facility Name: Rolla Nuclear Reactor

Inspection At: Nuclear Reactor Building, Rolla, MO

Inspection Conducted: January 25, 1979

Inspectors: J. L. Belanger 2-7-79

G. M. Christoffer 2-9-79

Approved By: J. A. Hind, Chief 2/9/79
Safeguards Branch

Inspection Summary

Inspection on January 25, 1979 (Report No. 50-123/79-01)

Areas Inspected: Routine, unannounced inspection of the approved security plan as it pertains to the protection of SNM, security organization, access control, alarm system, keys, locks, and hardware, communications, surveillance, procedures, security program review, and protection against radiological sabotage. The inspection involved 18 inspector-hours onsite by two NRC inspectors.

Results: Of the eleven areas inspected, no apparent items of non-compliance were identified in ten areas; one item of noncompliance was identified in one area (access controls - Paragraph 6). This item is considered to be a deficiency.

7903120274