



MATERIAL TRANSMITTED HERewith
CONTAINS 2.790 INFORMATION
UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

DEC 28 1978

In Reply Refer To:

RII:KHB

50-250/78-31

50-251/78-31

Florida Power and Light Company
Advanced Systems and Technology
ATTN: Dr. R. E. Uhrig, Vice President
P. O. Box 529100
Miami, Florida 33152

Gentlemen:

This refers to the inspection conducted by Mr. K. H. Besecker of this office on December 5-7, 1978 of activities authorized by NRC Operating License Nos. DPR-31 and DPR-41 at Turkey Point 3 and 4 and to the discussion of our findings held with Mr. H. E. Yaeger at the conclusion of the inspection.

The area examined during this inspection was your program for safeguarding special nuclear material under the applicable provisions of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials." Within this area, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

During the inspection, it was found that certain activities under your license appear to be in noncompliance with NRC requirements. These items and references to pertinent requirements are listed in the Notice of Violation enclosed herewith as Appendix A. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Details of activities involving safeguards and security measures are exempt from disclosure in accordance with 10 CFR 2.790(d). Therefore, your response should be incorporated in a separate paper and referenced in your reply.

7903070066

MATERIAL TRANSMITTED HERewith
CONTAINS 2.790 INFORMATION

Florida Power and Light Company


-2-

DEC 28 1979

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, activities involving safeguards and security measures are exempt from public disclosure; therefore, the enclosures to this letter with the exception of the report cover page, which is an inspection summary, will not be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,


W. B. Kenna, Chief
Safeguards Branch

Enclosures:

1. Appendix A, Notice of Violation
(Exempt from Disclosure)
2. Inspection Report Nos. 50-250/78-31
and 50-251/78-31
(Exempt from Disclosure)
3. Inspection Summary
(Not Exempt)

cc w/encls:

Mr. H. E. Yaeger, Plant Manager
Turkey Point Plant
P. O. Box 013100
9250 West Flagler Street
Miami, Florida 33101