

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 50-213/78-30

Docket No. 50-213

License No. DPR-61 Priority -- Safeguards Group 4
Category C

Licensee: Connecticut Yankee Atomic Power Company

P. O. Box 270

Hartford, Connecticut 06101

Facility Name: Haddam Neck Plant

Inspection at: Haddam Neck, Connecticut

Inspection conducted: December 11-14, 1978

Inspectors: *W. W. Madden*
W. W. Madden, Physical Security Inspector

1/26/79
date signed

date signed

date signed

Approved by: *W. W. Devlin*
W. W. Devlin, Chief, Security and
Investigation Section, Safeguards Branch

1/26/79
date signed

Inspection Summary:

Inspection on December 11-14, 1978 (Report No. 50-213/78-30)

Areas Inspected: Routine, unannounced physical security inspection by one regional based inspector. The inspection included: implementation of accepted Security Plan and applicable sections of 10 CFR 73.55 relative to: Security Plan, Security Organization, Physical Barriers, Access Controls, Detection Aids, Communications, Testing and Maintenance and Response Requirements. IE Bulletin 78-17, "Inadequate Guard Training" was also reviewed. This inspection was initiated during regular hours and involved 30 inspector-hours onsite by one regional based inspector.
Results: No items of noncompliance were identified.