NRC FORM 591M PAR	रा 1			CLEAR REGULATORY	COMMISSION			
(07-2012) 10 CFR 2.201	SAFETY INSPECTION	REPORT AN		SPECTION				
1. LICENSEE/LOCATION	INSPECTED:		2. NRC/REGIONAL OFFICE					
Midwest Division- RBH, LLC d/b/a Belton Regional Medical Center 17065 S. 71 Hwy. Belton, MO 64012			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352					
REPORT NUMBER(S)			Cisic, 12 00332-4332					
3. DOCKET NUMBER(5)		4. LICENSE NUMBER	(S)	5. DATE(S) OF INSPECTI	ОИ			
030-18606		24-24405-01		9/27/201	9			
Pegulatory Commissio	examination of the activities conduct on (NRC) rules and regulations and the sentative records, interviews with pers	e conditions of your	license. The inspection consist	ed of selective examinat	ions of			
1. Based on t	the inspection findings, no violations v	were identified.						
2. Previous v	Previous violation(s) closed.							
non-repetit	The side form (a) are sifeably described to you by the increaser as non-cited violations, are not being cited because they were self-identified							
	Non-cited violation(s) were discus-	sed involving the follo	owing requirement(s):					
cited in ac with 10 CF	s inspection, certain of your activities, cordance with NRC Enforcement Pol FR 19.11. s and Corrective Actions)	as described below icy. This form is a NC	and/or attached, were in violatio DTICE OF VIOLATION, which m	on of NRC requirements nay be subject to posting	and are being in accordance			
			,		表 []			
					e a Visite			
	C	atement of Corre	ective Actions					
	ithin 30 days, the actions described by	y me to the Inspector	will be taken to correct the viol		equested.			
	Allia OO daa ay ay ay ay	y me to the Inspector tents of 10 CFR 2.20 that no further writter	will be taken to correct the viol					
date when full compli	othin 30 days, the actions described by made in accordance with the requirem interest will be achieved). I understand	y me to the Inspector tents of 10 CFR 2.20 that no further writter	r will be taken to correct the viol of (corrective steps already take on response to NRC will be requi		equested.			
date when full compli	othin 30 days, the actions described by made in accordance with the requirem interest will be achieved). I understand	y me to the Inspector tents of 10 CFR 2.20 that no further writter	r will be taken to correct the viol of (corrective steps already take on response to NRC will be requi		equested.			

NRC FORM 591M PART 3 U.S. NUCLEAR REGULATORY COMMISSION (07-2012) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
LICENSEE/LOCATION INSPECTI		2. NRC/REGIONAL OFFICE					
Midwest Division- RBH, d/b/a Belton Regional Me 17065 S. 71 Hwy. Belton, MO 64012	dical Center		Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352				
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S	S)	5. DATE(S) OF INSPECTION			
030-18606		24-24405-01		September 27, 2019			
6. INSPECTION PROCEDURES USED 87131		7. INSPECTION FOCUS AREAS All					
	SUPPLEM	ENTAL INSPECT	ION INFORMATION				
1. PROGRAM CODE(S) 02120	2. PRIORITY 3	3. LICENSEE CONTACT Joshua McIlvian- RSO		4. TELEPHONE NUMBER (816) 348-1200			
✓ Main Office Inspection Next Inspection Date: September 27, 2022							
Field Office Inspec	otion						
Temporary Job Sit	e Inspection	1.7					
PROGRAM SCOPE This was an unannounced, routine inspection of a regional hospital authorized to use byproduct material under 10 CFR 35.100, 200, and 300 at its campus in Belton, Missouri. At the time of the inspection, the licensee performed a comprehensive spectrum of diagnostic and therapeutic administrations of radiopharmaceuticals. The nuclear medicine department was staffed with one full time and one part-time technologist that performed seven procedures per day from Mondays to Fridays. Also the licensee administered I-131 (under 30 microcuries) not used for therapy, just uptake imaging. The licensee retains a consultant health physicist to perform annual audits and of the radiation safety program and calibrations. PERFORMANCE OBSERVATIONS The inspector toured the facilities to evaluate the licensee's measures for material security, hazard communication, and exposure control. The inspector observed the preparation and administration of two heart rest tests. The inspector conducted independent and confirmatory surveys, and found no residual contamination or exposures to members of the public in excess of regulatory limits. The inspector also reviewed a selection of nuclear medicine records, personnel dosimetry, quarterly audits, inventory, leak test, linearity, accuracy, and RSC meetings minutes. No violations of NRC requirements were identified as a result of this inspection.							