



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

TERA

January 17, 1979

In Reply Refer To:

RIV

Docket No. 50-498/Rpt. 78-16  
50-499/Rpt. 78-16

Houston Lighting and Power Company  
ATTN: E. A. Turner, Vice President  
Power Production Construction  
and Technical Services  
Post Office Box 1700  
Houston, Texas 77001

Gentlemen:

Thank you for your letter of January 8, 1979, in response to our letter dated November 15, 1978, and the attached Notice of Violation. As a result of our review, we find that additional information, as discussed with your Mr. T. D. Stanley during a telephone call on January 16, 1979, is needed. Specifically, your descriptions of recurrence control measures for the three items of noncompliance should be expanded to state how the measures are accomplished and documented and if the measures are in addition to routine quality assurance program requirements.

Should you have any questions concerning this matter, we will be pleased to discuss them with you.

Sincerely,

W. C. Seidle, Chief  
Reactor Construction and  
Engineering Support Branch

7901250361