



February 22, 1979

L79-148

FILE: RR 2 (NP-33-78-100,
NP-33-78-125, NP-30-78-01)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Licensee Event Reports 78-083 (NP-33-78-100), 78-107 (NP-33-78-125), and 78-066 (NP-30-78-01), which have been revised to indicate the corrected cause codes and cause subcodes in blocks 12 and 13, respectively. There has been no change made to the supplemental information sheets accompanying these Licensee Event Reports. The revisions are indicated by a "1" in the left margin.

Please replace your previous copies of Licensee Event Reports 78-083, 78-107 and 78-066 with the attached revised copies.

Yours truly,

A handwritten signature in cursive script that reads 'Terry D. Murray'.

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies each LER

Mr. William G. McDonald, Director
Office of Management Information
and Program Control
Encl: 3 copies each LER

7903050 337

A002
S/11
5