

LICENSEE EVENT REPORT

CONT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5	
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER								25	26	LICENSE TYPE				30	57	CAT	58

0	1	L	0	5	0	-	0	3	2	4	0	5	0	7	7	9	0	6	0	4	7	9
7	8	9	REPORT SOURCE		60	61	DOCKET NUMBER				68	69	EVENT DATE			74	75	REPORT DATE				80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing P.T.1.3.1 PC, MSIV RPS Switch Calibration, the limit switches on

0 3 2B21-F022A, B and D were found out of tolerance. The required limit is < 1.65 inches

0 4 of travel, which corresponds to < 10% of full open. The three switches operated at

0 5 2.25, 2.15 and 2.15, respectively. It is felt that these switches may have been set

0 6 up incorrectly when initially adjusted.

0 7 Technical Specification 2.2.1 a.d 6.9.1.9a.

0	9	S	D	X	Z	I	N	S	T	R	U	S	Z
7	8	9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER		EVENT YEAR		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE	
7 9		7 9		X		Z		I N S T R U		S		Z	
17		21 22		23		24 26		27		28 29		30 31	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	
E 18		Z 19		Z 20		Z 21		0 0 0 0 22		N 23		4 24	
33 34		35 36		37 38		39 40		41 42		43 44		45 46	
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		REVISION NO.		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISED	
N 25		N 0 0 7 46		0 32		0 2 7 26		0 3 29		L 30		0 32	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The three limit switches were adjusted per P.T.1.3.1 PC and left in a satisfactory

1 1 condition. Twelve other valve limit switches were checked before this P.T. was per-

1 2 formed, and all were found to be good. P.T.1.3.1 PC is a new procedure, and its

1 3 performance should prevent future occurrences of this nature.

1	5	H	0	0	0	NA	B	Periodic Test	
7	8	9	% POWER			30	31	32	
FACILITY STATUS		OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION	
H 28		NA 30			B 31			Periodic Test 32	
28		44			45			80	

1	6	Z	Z	NA	NA
7	8	9	ACTIVITY CONTENT		36
RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
Z 33		Z 34		NA 36	
33		34		44	

1	7	0	0	0	Z	NA
7	8	9	PERSONNEL EXPOSURES		39	
NUMBER		TYPE		DESCRIPTION		
0 0 0 37		Z 38		NA 39		
37		38		60		

1	8	0	0	0	NA
7	8	9	PERSONNEL INJURIES		41
NUMBER		DESCRIPTION			
0 0 0 40		NA 41			
40		41		80	

1	9	Z	NA
7	8	9	43
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION	
Z 42		NA 43	
42		43	

2	0	N	NA
7	8	9	45
PUBLICITY		ISSUED DESCRIPTION	
N 44		NA 45	
44		45	

2232 177

7906070291

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-6701

NRC USE ONLY