

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company
McGuire Unit 1

License No. CPPR-83

Based on the NRC inspection February 28 through March 2, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by 10 CFR 50, Appendix "B", Criterion V and as implemented by DPC Topical Report "Duke 1-A" Section 17, paragraph 17.1.5, activities affecting quality shall be prescribed by documented instructions, procedures or drawings.

Contrary to the above, main steam safety valves were assembled July 23, 1978 without documented instructions.

This is an infraction.

2228 057

7906160041

~~79061600~~

Q