LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOOM I I I I I I I I I
	CONTROL BLOCK:
CON'T	9 LICENSEE CODE 14 75 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58
0 1	SOURCE L 60 5 0 0 0 3 6 8 7 0 7 1 3 7 9 8 0 8 0 2 7 9 9
0 2	L Review revealed that the Station Batteries Surveillance Inspection
0 3	required quarterly per T.S. 4.8.2.3.2b, was not performed on schedule.
0 4	The test was originally scheduled for 5/22/79, it was performed on
0 5	6/27/79. The schedule deviation was discovered on 7/13/79. Other
0 6	occurrences involving surveillance schedule deviations are
0 7	LER 50-368/79-649, 79-041, & 78-024. Reportable per T.S. 6.9.1.9c.
08	
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	1) LERIRO EVENT YEAR SEQUENTIAL REPORT NO. CODE 1 TYPE NUMBER NO. 10 15 6 0 13 L 1 1 1 1 1 1 1 1 1
	ACTION FUTURE EFFECT SHUTDOWN 22 26 27 28 29 30 31 32 TAKEN ACTION ON PLANT SHUTDOWN COMPONENT NPRD-4 PRIME COMP
	HOURS 22 SUBMITTED FORM SUR SUPPLIER MANUFACTURER 33 15 15 15 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 17 19 19 19 19 19 19 19 19 19 19 19 19 19
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The surveillance was not conducted on schedule due to oversight. The
11	importance of the surveillance program was discussed with the cognizant
1 2	supervis r. Administration of the Surveillance Program is in the process
1 3	of being centralized for better control.
14	
1 5	ACILITY TITATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
1 6 A	TIVITY CONTENT 12 13 44 45 46 80 LOCATION OF RELEASE 36 NA NA LOCATION OF RELEASE 36
177	PERSONNEL EXPOSURES 10 0 0 0 0 0 0 0 0 0
8	PEHSONNEL INJURIES 13
1 8	NUMBER 0 0 0 0 40 NA
8 1	OSS OF OR DAMAGE TO FACILITY (43) POST OF OR DAMAGE TO FACILITY (43) RO
1 9	Z J@ NA
2 0 1	PUBLICITY SUED DESCRIPTION 45 NRC USE ONLY
8 5	10
	NAME OF PREPARER Chris N. Shively PHONE: 501/968-2519
	2114 246
	20000