

FS&EB ACTION CONTROL FORM

A. Action Code CDR#148
 Name of Licensee and Facility Metropolitan Edison Co. (TMI 1)
 Docket No. or License No. 50-289
 Title OC coverage during inspection and test of protective relay
System and Associated Circuits
 Origin Licensee Date Rec'd 8/10/73


B. FS&EB Branch Coordinator:
 Bryan _____ Dreher X
 Ellis _____ Paulus _____
 Completion Requested by _____

C. Action Requested of:
 ADREMP _____ M&PPOB _____ EPB _____ RPB _____ ADCO _____
 OB _____ CB _____ TAB _____ OOE _____ Region I
 Date Requested 8/10/73 Completion Requested by _____
 Reference CDR dated 8/6/73

D. Action Requested In accordance with PI 0600/6, 'Construction Deficiency Reporting', The Metropolitan Edison Deficiency Report of 8/6/73, covering the apparent breakdown in their QA program with regard to inspection and testing of protective electrical equipment and circuitry, is being assigned to Region I for evaluation of technical adequacy of the corrective action being taken and final resolution of the deficiency.

E. Date Action Completed _____
 Close-out (Date & Method) _____
 Comments: If completion date is not consistent with your work schedule, please let us know.

1557 336


 J. G. Davis, Deputy Director
 for Field Operations
 Directorate of Regulatory Operations

0911070640

Handwritten initials